



Set Up Instructions

WLM-2000V


Step 1: Assemble straight poles by pressing and pushing together.




Step 2: Connect all corner sections to curved and straight sections of the frame by matching shape symbols on pipes.



Step 3: Insert center support pole.



Step 4: Insert the feet that came with the display into the corners of base to complete assembled frame shown.



Step 5: Unzip print and lay image face up. Slide print onto frame like a pillow case. Pull and stretch the graphic below the bottom cross bar and zip closed under the cross bar.

